



**Auslay Flooring - Dura Collection - Southern Blackbutt 1220mm x 178 mm - Wet  
Sliptest KO151122-2**

**15 Nov 2022**

**Slip Resistance Classification of New Pedestrian Surfaces - AS4586:2013 Appendix A**

Date Tested:	15 Nov 2022
Test Report Number:	KO151122-2
Client Name & Billing Address:	Auslay Industries Pty Ltd - 9/133 South Pine Road, Brendale Queensland, 4500
Surface Tested : (Samples and Test Information Supplied by Client)	Dura Collection - Southern Blackbutt 1220mm x 178 mm SKU: 1179-1 / SP0975-21
Wet Pendulum Test carried out using :	Slider 96 (4S) Rubber slider
Testing Officer / Approved Signatory:	Kathryn Ording
Pendulum in use - Calibration Date :	#0604 - Munro-Stanley Portable Skid Tester (C : 02.02.2022)
Signature of Approved Signatory :	

**Test Results :**

Sample No.	Swing 1	Swing 2	Swing 3	Swing 4	Swing 5	Mean BPN of last 3 swings :	SCV :	Surface Picture
Plank 1A	46	46	45	45	45	45	N/A	
Plank 1B	45	45	44	44	44	44	N/A	
Plank 1C	46	46	45	45	45	45	N/A	
Plank 2A	45	45	45	45	45	45	N/A	
Plank 2B	45	45	45	44	44	44	N/A	

Reported SRV For Test Area : 45

CLASSIFICATION using Slider 96 (4S Slider) P4 = 45 - 54

Accredited for Compliance with ISO/IEC 17025. The information presented herein and on the Sliptest Report is copyright and is protected by copyright law, any reproduction of this information and test report except in full is prohibited. Sliptest Australia Pty. Ltd. performed this on site test with reference to the following Australian Standard testing criteria, of AS 4586:2013 Classification of new pedestrian surface materials. Appendix A - Wet Pendulum Test Method and Hand Book HB 198: 2014 with reference to AS/NZS 4663: 2004 Slip Resistance measurement of existing pedestrian surfaces and HB 197: 1999. These results to not account for Future Wear, Maintenance or Contamination of this surface once in-situ.

Page 1 of 1 - END OF REPORT